

| | | |
|---|------------------|---|
|  | Doc. nr. : SK-70 |  |
| | Page : 1 of 1 | |
| | Revision nr. : 6 | |
| | Approved by : BV | |
| <p align="center">Test report Martindale Abrasion NS-EN 12947-2 :1999</p> | | |

| | | | |
|---|--|---------------------------------------|----------------------------|
| Client Crevin,s.a. Pol. Ind. Santa Margarita I C/ Llobregat, 21 08223 TERRASSA Spania | | Product URUS-FR | |
| | | Product specification - tested object | |
| Client's reference Pep Margarit | | R-no. R15456 | |
| Date 20.05.2015 | Date of receipt, tested object 12.05.2015 | Test completed date 20.05.2015 | Rev. no. / Rev. date 0/ |

Manufacturer:

Composition:

Pressure : 795 g(12 kPa) Type felt: Woven

The samples are conditioned at 20 degrees C and 65 % relative humidity for 18 hours

Determination of the abrasion resistance of textiles on a Martindale testmachine according to NS-EN 12947-2. Circular specimens of fabric are abraded against a reference fabric.

For woven fabrics the resistance to abrasion is estimated by number when two threads are broken.

For pile fabrics the resistance to abrasion is estimated by the number of cycles when the pile is fully worn off. For nonwovens the resistance to abrasion is estimated by the number when there is a hole of 0.5mm.

The average of four samples gives the results.

| |
|--|
| <p>Sample no. 1: 34000</p> <p>Sample no. 2: 34000</p> <p>Sample no. 3: 34000</p> <p>Sample no. 4: 34000</p> <p>Average 4 Samples: 34000</p> |
|--|

Comments:

Deviations from test standards: 3 Yarns breaking



Bård Vestre
Manager